



# End-of-Sale and End-of-Life Announcement for the Cisco CSS 11000 Series Content Services Switch

Cisco Systems® announces the end-of-life of the Cisco® CSS 11000 Series Content Services Switch. The last day to order the Cisco CSS 11000 is December 1, 2003. Customers will continue to receive support from the Cisco Technical Assistance Center (TAC) until December 1, 2008. Table 1 describes the end-of-life milestones, definitions, and dates for the Cisco CSS 11000 Series.

Customers are encouraged to migrate to the Cisco CSS 11500 Series or Cisco Content Switching Module (CSM) for the Catalyst® 6500 Series Switch, which offer extended features, performance, and scalability. Information about these products is available at: [www.cisco.com/go/css11500](http://www.cisco.com/go/css11500) and [www.cisco.com/go/csm](http://www.cisco.com/go/csm). Tables 3 and 4 provide relevant information for migrating from the Cisco CSS 11000 Series to the Cisco CSS 11500 Series or CSM.

Table 1 End-of-Life Milestones and Dates for the Cisco CSS 11000 Series

Milestone	Definition	Date
<b>End-of-Life Announcement Date</b>	The date the end-of-sale and end-of-life announcement is distributed to the general public.	June 17, 2003
<b>End-of-Sale Date</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	December 17, 2003
<b>Last Shipment Date</b>	The last-possible date that Cisco and/or its contract manufacturers will ship the affected product.	January 12, 2004
<b>End-of-Software Maintenance Releases Date</b>	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	December 17, 2004
<b>End-of-Routine Failure Analysis Date</b>	The last possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	December 17, 2004
<b>End-of-New Service Attachment Date</b>	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	December 17, 2004
<b>End-of-Service Contract Renewal Date</b>	The last date to extend or renew a service contract for the product. The extension or renewal period cannot extend beyond the last date of support.	September 17, 2008
<b>Last Date of Support</b>	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	December 17, 2008



Table 2 Product Part Numbers Affected by this Announcement

End-of-Sale Product Part Number	Product Description
CSS-11051-AC	CSS 11051, 8 pt FE (TX), 128 MB, HD, AC
CSS-11052-AC	CSS 11052, 8 pt FE (TX), 1 pt GE (SX), 128 MB, HD, AC
CSS-11151-AC	CSS 11151, 12 pt FE (TX), 128 MB, HD, AC
CSS-11152-AC	CSS 11152, 16 pt FE (TX), 128 MB, HD, AC
CSS-11153-AC	CSS 11153, 12 pt FE (TX), 4 pt FE (FX), 128 MB, HD, AC
CSS-11154-AC	CSS 11154, 12 pt FE (TX), 2 pt GE (SX with 8 MB), 128MB, HD, AC
CSS-11155-AC	CSS 11155, 12 pt FE (TX), 2 pt GE (SX with 16 MB), 128 MB, HD, AC
CSS-11151-256M-AC	CSS 11151, 12 pt FE (TX), 256 MB, HD, AC
CSS-11152-256M-AC	CSS 11152, 16 pt FE (TX), 256 MB, HD, AC
CSS-11152-256M-DC	CSS 11152, 16 pt FE (TX), 256 MB, HD, DC
CSS-11153-256M-AC	CSS 11153, 12 pt FE (TX), 4 pt FE (FX), 256 MB, HD, AC
CSS-11154-256M-AC	CSS 11154, 12 pt FE (TX), 2 pt GE (SX with 8 MB), 256 MB, HD, AC
CSS-11155-256M-AC	CSS 11155, 12 pt FE (TX), 2 pt GE (SX with 16 MB), 256 MB, HD, AC
CSS-11155-256M-DC	CSS 11155, 12 pt FE (TX), 2 pt GE (SX with 16 MB), 256 MB, HD, DC
CSS-11151-FD-AC	CSS 11151, 12 pt FE (TX), 128 MB, FD, AC
CSS-11152-FD-AC	CSS 11152, 16 pt FE (TX), 128 MB, FD, AC
CSS-11152-FD-DC	CSS 11152, 16 pt FE (TX), 128 MB, FD, DC
CSS-11153-FD-AC	CSS 11153, 12 pt FE (TX), 4 pt FE (FX), 128 MB, FD, AC
CSS-11154-FD-AC	CSS 11154, 12 pt FE (TX), 2 pt GE (SX with 8 MB), 128 MB, FD, AC
CSS-11155-FD-AC	CSS 11155, 12 pt FE (TX), 2 pt GE (SX with 16 MB), 128 MB, FD, AC
CSS-11155-FD-DC	CSS 11155, 12 pt FE (TX), 2 pt GE (SX with 16 MB), 128 MB, FD, DC
CSS-CONSOLE-KIT=	Accessory Kit for CSS-11x5x (adapters/cable/etc.)
CSS-RACKMOUNT-KIT=	Accessory Kit for CSS 11000 (adapters/cable/ears/etc.)
PWR-CSS8-850-DC=	Spare 850W Power Supply (DC) for CSS-1180x
CSS-PWR-AUS	Power cable Australia, New Zealand
CSS-PWR-AUS=	Power cable Australia, New Zealand
CSS-PWR-EUR	Power cable Europe (excluding Italy, Switzerland, and United Kingdom)
CSS-PWR-EUR=	Power cable Europe (excluding Italy, Switzerland, and United Kingdom)
CSS-PWR-ISR	Power cable Israel



Table 2 Product Part Numbers Affected by this Announcement (Continued)

End-of-Sale Product Part Number	Product Description
CSS-PWR-ISR=	Power cable Israel
CSS-PWR-IT	Power cable Italy
CSS-PWR-IT=	Power cable Italy
CSS-PWR-JPN	Power cable Japan
CSS-PWR-JPN=	Power cable Japan
CSS-PWR-SA	Power cable South Africa, India
CSS-PWR-SA=	Power cable South Africa, India
CSS-PWR-SWZ	Power cable Switzerland
CSS-PWR-SWZ=	Power cable Switzerland
CSS-PWR-UK	Power cable United Kingdom, Hong Kong, Singapore
CSS-PWR-UK=	Power cable United Kingdom, Hong Kong, Singapore
CSS-PWR-USA	United States, Canada, South America
CSS-PWR-USA=	United States, Canada, South America
CSS8-SCM-MEM-128M=	CSS 11800 SCM 128 MB memory upgrade
CSS-PWR-CVR=	Blank power supply cover
DOC-7811766=	Cisco Content Services Switch Getting Started Guide
DOC-7811766=	Cisco Content Services Switch Getting Started Guide
DOC-7811424=	Cisco Content Services Switch Basic Config Gde (SW Ver 5.00)
DOC-7811424=	Cisco Content Services Switch Basic Config Gde (SW Ver 5.00)
DOC-7811624=	Cisco Content Services Switch Adv Config Gde (SW Ver 5.00)
DOC-7811624=	Cisco Content Services Switch Adv Config Gde (SW Ver 5.00)
DOC-7811425=	Cisco Content Services Switch Command Ref (SW Ver 5.00)
DOC-7811425=	Cisco Content Services Switch Command Ref (SW Ver 5.00)
DOC-7815146=	Cisco 11000 Ser Content Services Switch HW Installation Gde
DOC-7815146=	Cisco 11000 Ser Content Services Switch HW Installation Gde



## Product Migration Options

The recommended replacement for the Cisco CSS 11000 Series is the Cisco CSS 11500 Series (Table 3 and Table 4) or Cisco CSM (Table 5).

Table 3 Product Comparisons of the Cisco CSS 11050, CSS 11501, and CSS 11503

	Cisco CSS 11050	Cisco CSS 11501 (S)	Cisco CSS 11503
<b>Form Factor</b>	Fixed standalone	Fixed standalone	Modular standalone
<b>Rack Units</b>	2	1	2
<b>Full Feature Content Switching</b>	Yes	Yes	Yes
<b>Integrated Secure Sockets Layer (SSL)</b>	No	Yes (optional)	Yes (optional)
<b>Adaptive Session Redundancy</b>	No	Yes	Yes
<b>Local Load Balancing</b>	Servers, caches, Firewalls	Servers, caches, Firewalls	Servers, caches, Firewalls
<b>Site Activity</b>	Low	Low	Medium
<b>Maximum Gigabit Ethernet Ports</b>	1	1	6
<b>Fast Ethernet</b>	8	8	32

Table 4 Product Comparisons of the Cisco CSS 11150, CSS 11503, and CSS 11506

	Cisco CSS 11150	Cisco CSS 11503	Cisco CSS 11506
<b>Form Factor</b>	Fixed standalone	Modular	Modular standalone
<b>Rack Units</b>	2	2	2
<b>Full Feature Content Switching</b>	Yes	Yes	Yes
<b>Integrated SSL</b>	No	Yes (optional)	Yes (Optional)
<b>Adaptive Session Redundancy</b>	No	Yes	Yes
<b>Local Load Balancing</b>	Servers, caches, Firewalls	Servers, caches, Firewalls	Servers, caches, Firewalls
<b>Site Activity</b>	Medium	Medium	Medium/High
<b>Maximum Gigabit Ethernet Ports</b>	2	6	12
<b>Fast Ethernet</b>	16	32	80



Table 5 Product Comparisons of the Cisco CSS 11050, CSS 11150, and CSM

	Cisco CSS 11050	Cisco CSS 11150	Cisco CSM for Catalyst 6500
<b>Form Factor</b>	Fixed standalone	Fixed standalone	Integrated module
<b>Rack Units</b>	2	2	–
<b>Full Feature Content Switching</b>	Yes	Yes	Yes
<b>Integrated SSL</b>	No	No	Optional module
<b>Adaptive Session Redundancy</b>	No	No	Yes
<b>Local Load Balancing</b>	Servers, caches, Firewalls	Servers, caches, Firewalls	Servers, caches, Firewalls, VPN
<b>Site Activity</b>	Low	Medium	Highest
<b>Maximum Gigabit Ethernet Ports</b>	1	2	178
<b>Fast Ethernet</b>	8	16	528

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

#### Additional Information

For more information about Cisco products, contact your Cisco account manager and/or Cisco Channels Partner.

For more information about the Cisco End-of-Life Policy, go to:

[http://www.cisco.com/en/US/products/prod\\_end\\_of\\_life.html](http://www.cisco.com/en/US/products/prod_end_of_life.html)



Corporate Headquarters  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

European Headquarters  
Cisco Systems International BV  
Haarlerbergpark  
Haarlerbergweg 13-19  
1101 CH Amsterdam  
The Netherlands  
www-europe.cisco.com  
Tel: 31 0 20 357 1000  
Fax: 31 0 20 357 1100

Americas Headquarters  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-7660  
Fax: 408 527-0883

Asia Pacific Headquarters  
Cisco Systems, Inc.  
Capital Tower  
168 Robinson Road  
#22-01 to #29-01  
Singapore 068912  
www.cisco.com  
Tel: +65 6317 7777  
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the  
**Cisco Web site at [www.cisco.com/go/offices](http://www.cisco.com/go/offices)**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia  
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland  
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland  
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden  
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2003 Cisco Systems, Inc. All rights reserved. CCIP, CCSP, the Cisco Powered Network mark, the Cisco Systems Verified logo, Cisco Unity, Follow Me Browsing, FormShare, iQ Net Readiness Scorecard, Networking Academy, and ScriptShare are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, The Fastest Way to Increase Your Internet Quotient, and iQuick Study are service marks of Cisco Systems, Inc.; and Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, the Cisco IOS logo, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherSwitch, Fast Step, GigaStack, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, LightStream, MGX, MICA, the Networkers logo, Network Registrar, Packet, PIX, Post-Routing, Pre-Routing, RateMUX, Registrar, SlideCast, SMARTnet, StrataView Plus, Stratm, SwitchProbe, TeleRouter, TransPath, and VCO are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company.  
(0304R)

Printed in the USA